



Drainage_Harvey_Marsh Road



9/25/2020, 2:29:18 PM

1:4,514

- | | | | |
|---------------------------|---------------------------|--------------------------|-------------------------|
| Sussex_Co | — Normal Intermediate | Conveyances | ▲ Dummy Point, Outfall |
| — Depression Index | New Castle County - Upper | ▶ Other Conveyances | ▲ Dummy Point |
| — Depression Intermediate | — Depression Index | ▶ Guardrail Culvert | ■ Inlet, Outfall |
| — Normal Index | — Depression Intermediate | ▶ Roadway Culvert | ■ Inlet |
| — Normal Intermediate | — Normal Index | ▶ Driveway Culvert | ◆ Junction Box |
| Kent_Co | — Normal Intermediate | ▶ Hydraulic Connection | ● Manhole, Outfall |
| — Depression Index | WaterPolys | ▶ Pipe | ● Manhole |
| — Depression Intermediate | ■ Water | ▶ Swale | ● Pipe Connection |
| — Normal Index | ■ Marsh | Structures | ● Pipe End, Outfall |
| — Normal Intermediate | — FlowLine | ● Other Structures | ■ Pipe End |
| New Castle County - Lower | — MajorRivers | ● Culvert Point, Outfall | ● Swale Point, Outfall |
| — Depression Index | BMPs | ● Culvert Point | ● Swale Point |
| — Depression Intermediate | ■ Other BMPs | ■ Control Structure | ● Temporary Dummy Point |
| — Normal Index | ■ DeIDOT | | |



Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, (c) OpenStreetMap contributors, and the GIS User Community, Delaware Geological Survey